

# Oil Field Environmental Incident Summary

**Incident:** 20150416162432      **Date/Time of Notice:** 04/16/2015 16:24

**Responsible Party:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Name:** ERICKSON 34-32

**Field Name:** PORTAL

**Well File #:** 10256

**Date Incident:** 4/16/2015

**Time Incident:** 09:00

**Facility ID Number:**

**County:** BURKE

**Twp:** 164

**Rng:** 91

**Sec:** 32

**Qtr:** SW SE

**Location Description:**

**Submitted By:** Gary Watson

**Received By:**

**Contact Person:** Mark Bonnie  
5160 TENNYSON PARKWAY  
SUITE 3000 E  
PLANO, TX 75024

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 600 Feet

**Distance Nearest Water Well:** 600 Feet

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/12/2015

**Clean Up Concluded:** 4/18/2015

**Risk Evaluation:**

No immediate health hazard or explosion risk.

**Areal Extent:**

100' x 100' of light oil mist. No produced water was released.

**Potential Environmental Impacts:**

Minimal impact to county dirt road and cultivated land (harvested canola stubble).

**Action Taken or Planned:**

NDIC Inspector Jim Potts was notified via telephone. Will consult with NDIC, ND Health Department and landowner to determine best way to remediate area. Alternatives are burning affected canola stubble or scraping and hauling off affected soil and stubble. Surface owner has been identified and will be contacted.

**Wastes Disposal Location:** Approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 4/16/2015    **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from a vessel leak sprayed off location. Followup is necessary.

---

**Date:** 4/22/2015    **Status:** Awaiting Documentation

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

4/22/2015 at 16:15, on location. Based on impacted canola stubble, spray went southeast from wellpad, over county road 108th St NW and into field. Visible staining limited to canola stubble; no visible staining to ground itself in field. Vegetation in county road ditch also visibly stained. Staining is light enough that tilling of the field for planting should biodegrade any remaining impact. However, county road impact will not be tilled in, so a sample was requested from the report contact to determine the amount of staining remaining.

---

**Date:** 6/17/2015    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received sample results. TPH results below detection limits. No further follow-up required.